Historic Benton County Courthouse

Exterior Renovations and

First Floor Remodel



Restore the Exterior Facade to Protect Historical Materials

Repair Existing Systems and Provide Infrastructure for Future Work on Upper Floors.

Remodel First Floor to Provide Updated and Functional Facilities.

Protect the Existing Facility and Increase its Viability for Ongoing Occupancy

GOALS



- Air Quality and Asbestos Testing at First Floor Office Area
- Asbestos Abatement at First Floor Office Area
- Demolition of Existing Walls and Ceilings at First Floor
- Exploration of Existing Conditions

Phase I - Demolition



Existing Spiral Staircase, Unsupported Lintel, Abandoned Wiring & Pipes



Hight Jackson ASSOCIATES

Structural Failure at Second Floor Porch – Water Infiltration at First Floor



Discovery




Structural Failure at Second Floor Porch – Water Infiltration at First Floor



Discovery



Replacement of Structural Slab and Installation of Coating System



Hight Jackson ASSOCIATES

- Replace Below-Grade Waterproofing
- Replace the Existing Concrete Mow Strip
- Install Bullet Resistant Windows at First Floor
- Remove and Reset Protruding Limestone at Stair Wall and Verify Structural Conditions.
- Clean, Point and Repair or Replace Existing Brick and Limestone Veneer
- Reset and Level the Existing Limestone Parapet Cap Pieces
- Install Sealant in all Skyward Facing Limestone joints
- Clean and Paint Existing Steel Window Lintels.
- Stop water infiltration into Courthouse and Tower Entry

Phase II Exterior Restoration





Below Grade Waterproofing







Below Grade Waterproofing







Windows & Mow Strip






Brick Wall behind Limestone showed no signs of Structural Failure



Stair Wall Repairs




Limestone has been cleaned and Reset



Stair Wall Repairs















































Restoration



Hight Jackson ASSOCIATES

- Stop water infiltration into Courthouse and Tower Entry
 - Benton County Replaced the Existing Roof

• Brick on the North Side of the Tower was removed and Flashing was installed to eliminate leaks over the temporary holding area in the Tower.






- Replace the Existing Cooling Tower
- Repair the Existing Boiler Equipment and Upgrade Electrical System
- Provide Main Data Room at First Floor
- Provide Chase for Future Service Runs to Upper Levels
- Remodel of First Floor Office Area Currently Occupied by the Prosecuting Attorney

Phase III - Remodel & Service Improvements



- Replace the Existing Cooling Tower
 - Multi-Craft Contractors inspected the Cooling Tower and discovered that Significant Damage to some of the internal parts.
 - Under Phase III Work. A new Cooling Tower will be installed.




New Equipment will be Capable of Expansion



- Repair the Existing Boiler Equipment
 - Equipment will be Repaired and System will be flushed for proper functioning and maintenance.
- Upgrade Electrical System
 - Existing Electrical Panels require some Maintenance and are almost at maximum capacity.
 - New electrical wiring is being provided to the first floor renovated areas.
 - New electrical panel is being installed.




Remodel of First Floor Office Area





• Remodel of First Floor Office Area – Restore Plaster Ceilings at perimeter offices.





• Remodel of First Floor Office Area – Restore Plaster Ceilings at perimeter offices.





New cable tray and ductwork









